19. 20.

AIR QUALITY PERMIT **BONDING & INSURANCE**

DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt Governor

Kathleen Clarke Executive Director Lowell P. Braxton

1594 West North Temple, Suite 1210 PO Box 145801

AVS CHECK (4th Quarter-April, May, June)____(date)

Partial: XXX Complete: Exploration: Salt Lake City, Utah 84114-5801
801-538-5340
Inspection Date & Time: 5/16/2000 / 10:00a.m.-3:00p.m.-

801-359-3940 (Fax) Division Director 801-538-7223 (TDD) Date of Last Inspection: 4/4,5/2000

Mine Name: <u>Sunnyside Refuse/Slurry</u> County: <u>C</u>	Carbon Permit	Numbe	er: ACT/007	<u>/035</u>
Permittee and/or Operator's Name: Sunnyside Coge	eneration Associ	iates	1112	<u> </u>
Business Address: P.O. Box 10, East Carbon, Utah				<u></u>
Type of Mining Activity: Underground Surfac		p. Plan <u>t</u>	Other	
Company Official(s): Rusty Netz	C AAA IIC	p. 1 mii		-
- · · · · · · · · · · · · · · · · · · ·	O. 1.1()			
State Officials(s): Bill Malencik Federal Of		ne		
Weather Conditions: Windy, Cold, 60's, Partly	Cloudy			
Existing Acreage: Permitted-310 Disturbed-202	Regraded-	Seeded	- Bonded-	202
Increased/Decreased: Permitted Disturbed				
Status: _Exploration/_XXX_Active/_ Inactive/_ Te				
Reclamation (_Phase I/_Phase II/_Final Bor	id Release/_ Lia	D11111 <u>y 15</u>	94 Course Refus	e Road)
DEVIEW OF DEDICE DEDUCATION OF THE PROPERTY OF	o penium compl	TION DE	OLUBEA (ENTO	
REVIEW OF PERMIT, PERFORMANCE STANDARDS Instructions	& PERMIT CONDI	TION REC	JUIKEMEN 15	
1. Substantiate the elements on this inspection by checking the approximately 1.	opriate performance s	tandard.		
a. For complete inspections provide narrative justification for	any elements not f	ully inspec	cted unless elemen	t is not
appropriate to the site, in which case check N/A.				
b. For <u>partial inspections</u> check only the elements evaluated.2. Document any noncompliance situation by referencing the NOV is	and at the appropriat	e nerforma	ince standard listed	helow
3. Reference any narratives written in conjunction with this inspection	on at the appropriate	performan	ce standard listed b	pelow.
4. Provide a brief status report for all pending enforcement actions,	permit conditions, D	ivision Or	ders, and amendme	ents.
	EVALUATED	<u>N/A</u>	COMMENTS	NOV/EN
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE		Щ	Ц	Щ
2. SIGNS AND MARKERS3. TOPSOIL				Ц
3. TOPSOIL 4. HYDROLOGIC BALANCE:	[XX]	<u> </u>	<u>L.</u> l.	ш
a. DIVERSIONS	[XX]	r ı	[XX]	Гì
b. SEDIMENT PONDS AND IMPOUNDMENTS		[]	[XX]	[]
c. OTHER SEDIMENT CONTROL MEASURES		<u> </u>	[XX]	
d. WATER MONITORING	<u> </u>	<u> </u>		
e. EFFLUENT LIMITATIONS			\Box	$\overline{\Box}$
5. EXPLOSIVES		[XX]	\Box	
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[XX]	\Box	[XX]	
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS			[XX]	
8. NONCOAL WASTE	[XX]	\Box	\Box	
9. PROTECTION OF FISH, WILDLIFE AND			r 1	r 3
RELATED ENVIRONMENTAL VALUES		Ц		닏
10. SLIDES AND OTHER DAMAGE11. CONTEMPORANEOUS RECLAMATION	[XX]		<u> </u>	<u> </u>
12. BACKFILLING AND GRADING	<u>L_1</u>	<u> </u>	[]	 []
13. REVEGETATION	II	[]	[]	[]
14. SUBSIDENCE CONTROL	[]		급	1 1
15. CESSATION OF OPERATIONS	[]		[·]	[]
16. ROADS:			 !	
a. CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	\Box	[XX]	\Box
b. DRAINAGE CONTROLS	XX	\Box		\Box
17. OTHER TRANSPORTATION FACILITIES		\Box		\Box
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[]	[]	[_]	

INSPECTION REPORT

(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/035

DATE OF INSPECTION: 5/16/2000

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS

- -Conducted a partial inspection of the Sunnyside Cogeneration Surface Mine. The environmental control measures were functional.
- -Brian Burnett and Scott Childs are working with Pam on a new Chapter 1. Also, Brian is working on a test burn proposal. When he completes his work about the middle of July, he will send the proposal to DOGM for approval.
- -Sunnyside Cogeneration is looking into the possibility of screening Savage's coal waste.

4A. HYDROLOGIC BALANCE: DIVERSIONS

Disturbed and undisturbed diversions are shown on plate 7-6, individual designed diversions are on Appendix 7-3. The disturbed diversions include culverts, berms, and ditches.

A sampling of key diversions during the inspection did not uncover any maintenance problems. A new culvert was installed adjacent to slurry pond #1 on an ancillary road.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The disturbed area contains eleven impoundments, of which seven are sediment ponds. There are four slurry approved impoundments. Slurry cell one and two are non-MSHA impoundments. The east and west slurry cells are MSHA impoundments. All slurry cells are inactive. This occurred when the Sunnyside Mine closed and no longer washed coal in 1994. Furthermore, the slurry ditch has just been reclaimed in 1999 and no slurry will be conveyed to the slurry cells.

The sediment ponds and slurry cells were inspected and reports were reduced to writing.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

There are three small areas where designed silt fences and/or vegetation has been approved by the Division to provide sediment control.

- Area 1 South of the clear water pond, vegetation is the treatment.
- Area 2 South of the reclaimed coarse refuse road, silt fences and vegetation are the treatment.
- Area 3 Railroad culvert, adjacent up-slope, silt fence, and vegetation provides the treatment.

INSPECTION REPORT

(Continuation sheet)

Page <u>3</u> of <u>3</u>

#26

PERMIT NUMBER: ACT/007/035

Inspector's Signature

DATE OF INSPECTION: 5/16/2000

(Comments are Numbered to Correspond with Topics Listed Above)

There are other soil and sediment control devices including silt fences; however, these are redundant control measures. All such areas drain into approved sediment ponds. The silt fence was being repaired during the inspection. High winds this day were the problem and blew down part of the silt fence.

6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES

The permittee has an approved site to store spoil and tipple processing waste. Currently, spoil is stored in the decommissioned slurry cell as currently approved in the MRP. The waste is being placed in the slurry cell #1. When slurry cell #1 is filled, the operation will move to slurry cell #2.

Three sites were approved so that coal material would be stored on the spoil piles and not on the refuse pile.

7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

The permittee is currently mining the west slurry cell and contiguous refuse pile. No mining has started on the east slurry cell.

16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

An amendment has been approved by Pam Grubaugh-Littig on increasing the width of the primary road. The road will be extended to the north about 75'. A ditch currently designed and a culvert will also be moved. Advised the permittee to submit as-builts when the project is completed.

Note:	This inspection report does not constitute an affidavit of compliance with the regulatory program of	f the Division of Oil, Gas, and Mining.
Copy	of this Report:	
	Mailed to: Rusty Netz (Cogen)	Henry Austin (OSM
	Given to: Pam Grubaugh-Littig (DOGM)	Filed to: Price Field Office
	Date: May 17, 2000	